Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5067**

Resource Identification

Property Name(s): ..... Holland House {Current}
Property Date: ..... ca 1900
Address(s): ..... South Side of Route 603 {}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Foundation	Foundation - Piers	Brick	Foundation - Common Bond
Porch	Porch - 1-story, 1-bay	Wood	Porch - Post, Square
Roof	Roof - Gable, Side	Tin	Roof - Pressed Shingle
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Double-hung	Wood	Windows - 2/2
Chimneys	Chimneys - Interior end	Brick	Chimneys - Common Bond

Site Description: ..... The house is located in a rural area.

Secondary Resource Desc: There are two outbuildings associated with this house.

WUZIT Count:

No.	Wuzit Types	Historic?
1	Barn	Historic
1	Shed	Historic
1	House	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight **DHR Id#: 046-5067**

Individual Resource Information

WUZIT: ..... House

Est. Date of Construction:	1900 ca {Site Visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	2.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Built c. 1900, this two-story I-House features a wooden frame structural system that rests on brick piers with concrete block infill. The exterior is covered in weatherboard and the side-gabled roof is clad in pressed tin. There are two brick chimneys. A chimney is located at each interior end of the house and a third is on the central interior portion of the one-story rear addition. The one-story addition on the south elevation features a gabled roof and integral porch on the west façade. Square wooden posts on brick piers support the one-story hipped porch. Fenestration consists of two-over-two and one-over-one wooden double-hung sash windows.

WUZIT: ..... Shed

Est. Date of Construction:	1910 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: East of the house is a shed covered in weatherboard with a gabled roof clad in composition shingles.

WUZIT: ..... Barn

Est. Date of Construction:	1910 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	2.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: South of the house is a two-story barn with a weatherboard exterior and gabled roof clad in standing-seam metal.

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic
Subsistence/Agriculture

Historic Time Period(s): ..... P- Reconstruction and Growth (1865 to 1914)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5067**

Reference #: 1
Bibliographic RecordType: ..... Survey
Author: ..... CCR, Inc
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	5	VDHR	2004/07/01	Single Dwelling

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: .....

CRM Event # 3,
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: .....